


# COCON

## RELEASE NOTES



## Copyright Statement

No part of this publication or documentation accompanying this product may be reproduced in any form or by any means or used to make any derivative such as translation, transformation, or adaptation without the prior written permission of the publisher, except in case of brief quotations embodied in critical articles or reviews. Contents are subject to change without prior notice.

Copyright © 2020 by Televic Conference NV. All rights reserved.

The authors of this manual have made every effort in the preparation of this book to ensure the accuracy of the information. However, the information in this manual is supplied without warranty, either express or implied. Neither the authors, Televic Conference NV, nor its dealers or distributors will be held liable for any damages caused or alleged to be caused either directly or indirectly by this book.

## Trademarks

All terms mentioned in this manual that are known to be trademarks or service marks have been appropriately capitalized. Televic NV cannot attest to the accuracy of this information. Use of a term in this book should not be regarded as affecting the validity of any trademark or service mark.

# DOCUMENT HISTORY

Version	Date	Description
0.1	2019-05-28	Release notes version 6.0
1.0	2019-08-08	Release notes version 6.0.1
1.1	2019-11-07	Release notes version 6.1.0.30
1.1.1	2019-11-13	Added known limitations for version 6.1.0.32
1.1.2	2020-01-14	Release notes version 6.2.0.4
1.1.3	2020-03-11	Release notes version 6.3.0.10

# CONTENTS

Document history .....	3
RELEASE NOTES.....	<b>Error! Bookmark not defined.</b>
COCON 6.3.0.10.....	5
COCON 6.2.0.4.....	7
COCON 6.1.0.32.....	9
COCON 6.0.1.....	13
COCON 6.0.....	14

# COCON 6.3.0.10

## WHAT'S NEW

- Support for Confidea Flex Dual Delegate functionality
- Support for request session control
- Support for service call on Confidea FLEX

## FIXED ISSUES

- Fixed an issue where in rare occasions the CoCon Meeting Manager would crash when importing delegates in the database (COC-2741)
- Fixed an issue in the CoCon Nameplate Manager where after starting a prepared meeting and assigning a new delegate to a seat with a Plixus Nameplate during the meeting, the Nameplate is not updated (COC-2862)
- Fixed a UI issue with startup screen configuration in the CoCon Room Configurator (COC-2895)
- Fixed an issue with document view screen event in the default signage template (COC-2913)
- Added voting right API calls (COC-2931)
- Fixed an issue with different responses to the CoCon connect API call (COC-2936)
- Fixed an issue with a redundant pop-up message when saving a meeting template in the CoCon Meeting Manager (COC-519)
- The CoCon Room Server wizard now warns if the software version on the central unit is incompatible (COC-2799)
- Fixed an issue in CoCon Operator where the advanced request settings were not shown correctly (COC-2918)
- Fixed an issue where in some occasions, editing the database during a meeting could result in a delayed microphone on/off response (COC-2877)
- Fixed an issue where the next-to-speak indication was always enabled when starting a meeting (COC-2804)
- Fixed an issue where in rare occasions some meeting info is not available after the meeting and cannot be recovered (COC-2952)

## KNOWN LIMITATIONS

- In some occasions when the CoCon database holds multiple rooms, the CoCon Signage Screen does not follow the meeting state (COC-2987)

- The microphone LED is not blinking when the speech timer warning threshold has been reached (COC-2824)
- When an interpretation configuration is activated with "audience indication" activated, the monitoring of listeners is not updated correctly (UNIMM-3851)
- In some occasions the CoCon Web Signage may not show all seated delegates (COC-3003)

# COCON 6.2.0.4

## WHAT'S NEW

- Support for Confidea FLEX
- Added API calls for booth management

## FIXED ISSUES

- Improved performance on loading Plixus Nameplate images by removing the bitmap references in the delegate management (COC-2906)
- Improved indications in the CoCon Nameplate Manager when the system is busy processing an action (COC-2878)
- Fixed an issue where in some cases importing delegates via XLS file would fail (COC-2871)
- Fixed an issue where an unknown value would show up as 'unknown' on Plixus Nameplates (COC-2869)
- Update agenda timer indication on the CoCon Signage screen (COC-2778)
- Updated alignment of speaker list on the CoCon Signage screen (COC-2775)
- Allow any meeting to be put in prepared state (COC-2774)

## KNOWN LIMITATIONS

- The microphone LED is no longer blinking green when the speech timer warning time was reached and the LED color is set to green (COC-2679)
- Assigning a Plixus Nameplate to a seat requires the user to open and close initialization to update the status (COC-2645)
- In some cases backup nodes would be automatically set after activating the configuration (COC-1988)
- In the CoCon Nameplate application it is possible to delete a layout which was being used in an active meeting, although this does not affect the layouts nor active meeting itself (COC-1745)





# COCON 6.1.0.32

## WHAT'S NEW

- Configurable standby screen for uniCOS including Plixus video
- Configurable uniCOS UI tabs
- Added API calls to force a certain video stream to uniCOS units
- Added API call to remove or add multiple delegates from or to a seat
- Added API call to get full agenda details
- Added possibility to modify the default voting templates in CoCon Meeting manager
- Added new keyboard shortcut CTRL+E to edit a delegate in CoCon Meeting manager
- Added Current Speaker component in CoCon Signage
- Added second badge option for delegates
- Added title and seat nr in meeting delegates list in the CoCon Operator application
- Added a reply list component to CoCon Signage
- Added option in the CoCon Room Server wizard to disable CoCon logging
- Added configuration of default uniCOS tabs in the CoCon Room Configurator
- Added support for voting on multiple voting options
- Added Latin text for languages in the CoCon Interpreter application's language list
- Added support for delegate pictures in CoCon Signage
- Added a group voting results component in CoCon Signage
- Added support for viewing documents in CoCon Signage
- Any active microphone will now be turned off when an inserted badge is removed from a unit
- Any active microphone will now be turned off when a meeting has ended

## FIXED ISSUES

- Upload license files is now only possible through the central unit's web page (COC-2826)
- Fixed an issue where in some cases pausing and resuming a meeting could result in some seats without assigned delegates on CoCon Signage (COC2821)

- Fixed an issue where in some cases uniCOS units would still show the badge login screen after resending the meeting data (COC-2807)
- The CoCon Room server wizard now mentions Plixus Engine instead of Plixus Multimedia Engine (COC-2801)
- Fixed an issue with speaker list alignment on CoCon Signage (COC-2775)
- Fixed an issue where a meeting could only be put in prepared state when Plixus Nameplates are used (COC-2774)
- Fixed an issue where in some cases the CoCon Audio Routing application would show errors when creating a routing with external translation (COC-2772)
- Fixed an issue with the SetCustomButtonOnSeat API call (COC-2770)
- Fixed an issue where the meeting statistics and printout don't show an end date when pausing a meeting for a longer period (COC-2765)
- Fixed an issue where in rare occasions the CoCon Meeting Manager would get stuck when starting a meeting from the CoCon Operator application while enabling and disabling microphones (COC-2763)
- Fixed an issue with VIP delegates being treated as chairperson delegates in a voting session with hung vote options (COC-2762)
- Fixed an issue where the CoCon Video application is not functioning properly in the Microsoft Edge browser (COC-2754)
- Fixed a layout issue in CoCon Signage where some content was shrunk instead of filling the quadrant (COC-2753)
- Fixed an issue in CoCon Room Configurator where the default channel selector volume adjustment had no effect on the actual volume (COC-2752)
- Fixed an issue where in some cases importing a meeting Microsoft Word file in the CoCon Meeting Manager resulted in incorrect subitems in the meeting agenda (COC2750)
- Fixed a minor UI issue with the Language List component in CoCon Signage (COC-2742)
- Fixed an issue where in rare occasions the CoCon Signage application would show all microphones on where only one is activated (COC-2732)
- Fixed an issue with importing delegates through a file (COC-2731)
- Fixed an issue where in rare occasions the CoCon Operator application could hang when activating more microphones than the meeting options allow (COC-2729)
- Fixed an issue where in rare occasions the CoCon Operator application could hang when changing an active microphone's seat priority from delegate to chairman (COC-2727)
- Fixed an issue where in some occasions the CoCon Signage screen is not updated when adding a delegate to a seat during a voting session (COC-2725)
- Fixed an issue where in some occasions voting would remain possible after a user logged out using his fingerprint (COC-2723)
- Fixed an issue where a delegate could not vote after logging in during a voting session using external authentication (COC-2718)
- Fixed an issue with missing presence check when using external authentication such as fingerprint (COC-2716)

- Fixed an issue with retrieving voting results after stopping a voting in the CoCon Operator application (COC-2711)
- Improved UI in CoCon Signage to support multiple voting options (COC-2710)
- Fixed an issue with incorrect overall voting result when closing and reopening the CoCon Operator application (COC-2708)
- Fixed an issue with the SetCulpAddress API call (COC-2702)
- Fixed an issue where the interpretation preset would fail when the same display text is used more than once (COC-2698)
- Fixed a UI issue with some buttons in the CoCon Video application when using Mozilla Firefox as a browser (COC-2695)
- Fixed an issue where in some occasions a unit's microphone LED would keep blinking after changing the speech warning time while the microphone is activated with the CoCon Operator application (COC-2694)
- Set the default setting for Audience Indication to unchecked (COC-2693)
- Fixed an issue with response times in API calls to set the delegate speech times (COC-2691)
- Fixed an issue where in some occasions the Plixus Nameplate is not updated when a delegate logs in while a voting session is ongoing (COC-2690)
- Fixed an issue where in rare occasions a meeting could not be started from a template after updating the database (COC-2689)
- Fixed an issue where in some occasions a uniCOS unit would not switch to the voting tab automatically when a presence check is done (COC-2684)
- Fixed an issue where the CoCon Room Configurator did not follow the central unit's setting for the next person to speak indication (COC-2680)
- Fixed an issue where the Sync with Signage function was still available when a document was deleted or unselected (COC-2676)
- Fixed an issue with the CoCon Operator application not updating the conference settings in a fixed seating meeting (COC-2670)
- Improved indication of Plixus Nameplates on the CoCon Operator room layout and CoCon Signage (COC-2667)
- Fixed an issue with displaying right-to-left languages in the CoCon web applications (COC-2665)
- Fixed an issue with Dutch translation of speaker list in CoCon Signage (COC-2664)
- Fixed an issue where a microphone in the reply list could not be activated in the CoCon Operator application (COC-2660)
- Fixed an issue where in some cases the textual view would not display voting results by choice (COC-2651)
- Fixed an issue where in some occasions messages sent from the CoCon Operator application would not show up on uniCOS units (COC-2643)
- Fixed an issue with seat label positioning in CoCon Signage (COC-2638)
- Fixed an issue with enabling speech timer was not applied to all selected seats (COC-2635)

- Fixed an issue where messages showing missing or broken units would not show the seat number or booth ID (COC-2626)
- Improved device names in the CoCon Video application (COC-2613)
- Fixed an issue in the CoCon Room Configurator where -8dB was not selectable for the loudspeaker volume (COC-2609)
- Improved displaying voting result options in CoCon Signage (COC-2578)
- Fixed an issue in the CoCon Audio application where seats were selectable in an output group (COC-2576)
- Improved export statistics based on user selection (COC-2573)
- Improved logging of API calls (COC-2556)
- Fixed an issue where in case a chairman is changed to a delegate would not result in displaying the speech timer on the signage screen (COC-2554)
- Fixed an issue with displaying the voting entitled list on CoCon Signage (COC-2552)
- Improved room server information when trying to connect with an application of a higher version (COC-2398)
- Improved consistency in Plixus Nameplate images when using different meeting login methods and some badges are inserted and some are not (COC-2147)
- Improved service call events through API (COC-1800; COC-2641)
- Fixed an issue where in some cases + or – could not be used as agenda item characters in the CoCon Operator application (COC-1393)
- Fixed an issue with the use of authority badges together with uniCOS units (COC-27)

## KNOWN LIMITATIONS

- The microphone LED is no longer blinking green when the speech timer warning time was reached and the LED color is set to green (COC-2679)
- Assigning a Plixus Nameplate to a seat requires the user to open and close initialization to update the status (COC-2645)
- In some cases backup nodes would be automatically set after activating the configuration (COC-1988)
- In the CoCon Nameplate application it is possible to delete a layout which was being used in an active meeting, although this does not affect the layouts nor active meeting itself (COC-1745)

# COCON 6.0.1

## FIXED ISSUES

- Fixed an issue where casting a vote was not possible via external authentication after the vote has started (COC-2718)
- Fixed an issue where voting was still possible on uniCOS units after logging out (COC-2723)
- Improved visibility of the CoCon Room Server version prior to connecting to it via a CoCon application (COC-2398)
- Fixed an issue where a delegate would show up as anonymous delegate after changing the vote weight during a meeting (COC-2580)
- Fixed an issue where -8dB was not selectable in the CoCon Room Server application (COC-2609)
- Fixed an issue where the signage screen is not updated if a delegate is put on a seat during a voting (COC-2725)

## FIXED ISSUES

- Sync packages in the camera protocol messages show unit number instead of seat number when connecting to the CoCon Room Server API (COC-2473)

# COCON 6.0

## WHAT'S NEW

- Support for VIP delegate mode in CoCon Operator, Meeting Manager and Signage
- Support for multi-stream video routing through a web based CoCon Video Manager application
- Support for Intercom between delegates and/or interpreter booths
- Support for Dante™-on-seat, use external audio channels with discussion capabilities
- Support for middle name in the CoCon delegate database
- Support for Microsoft SQL 2016
- Support for Hebrew in CoCon Nameplate Manager, CoCon Signage Manager and CoCon Video Manager web applications
- Support for TLVCAM9 camera protocol
- Support for selecting multiple interpreter desks and adding them to a booth in the CoCon Room Configurator (COC-2400)
- Removed initialization from the CoCon Room Configurator, initialization is only available via the central unit's web page (COC-2391)
- Support for up to 16 voting options in the CoCon Meeting Manager and CoCon Operator application (COC-2371)
- Support for LED behavior for the next-in-line in the request list, this can now be configured as blinking or not blinking (COC-2132)

## FIXED ISSUES

- Fixed an issue with voting results in the CoCon Operator application (COC-2651)
- Fixed an issue with storing default Plixus Nameplate layouts in the CoCon Nameplate Manager (COC-2650)
- Fixed an issue where in some cases messages sent from CoCon Operator were not received on uniCOS devices (COC-2643)
- Fixed an issue with user mapping in Microsoft SQL 2016 (COC-2640)
- Fixed an issue in the CoCon Operator application where in case a Plixus Nameplate is assigned to a seat, 2 microphones were shown instead of 1 (COC-2637)

- Fixed an issue where in some cases the Plixus nameplate capability was not shown in the CoCon Applications (COC-2634)
- Fixed an issue where in some cases a missing unit returned but was not updated in the CoCon Operator application (COC2629)
- Fixed an issue in the CoCon Nameplate Manager where duplicate names were not updated after import (COC-2615)
- Fixed an issue with speech timers not being updated in the CoCon Signage and CoCon operator application (COC-2611)
- Fixed an issue with missing -8dB volume setting in the CoCon Room Configurator (COC-2609)
- Fixed an issue where incorrect data for IsVotingChoiceNumber was stored in the voting template (COC-2600)
- Fixed an issue with delays in API badge notifications (COC-2598)
- Fixed an issue with component UI in CoCon Signage Manager (COC-2597)
- Fixed an issue with voting UI in the CoCon Meeting Manager (COC-2595)
- Fixed an issue where in rare occasions the CoCon Meeting Manager would go into offline mode after importing a meeting template (COC-2594)
- Reordered and renamed microphone modes in the CoCon Room Configurator (COC-2586)
- Fixed an issue with displaying voting results in the voting result PDF after changing the vote weight during a meeting (COC-2580)
- Fixed an issue where in rare cases a delegate is shown twice in the CoCon Operator Application (COC-2575)
- Fixed an issue where in some cases the CoCon Operator Application is not closing as expected after an XPS meeting export (COC-2574)
- Fixed an issue with saving an interpreter configuration's description in the CoCon Interpreter Application (COC-2563)
- Fixed an issue in the CoCon Room Configurator to allow changing room layout names (COC-2557)
- Fixed an issue in the CoCon Operator application where the uniCOS UI language was reset to English instead of the default language after a software reset of the device (COC-2546)
- Fixed an issue in the CoCon Room Configurator where it was unclear how to configure the fallback for the reply buttons on certain units (COC-2545)
- Fixed an issue with configuring Plixus Nameplates after a meeting was created with the API (COC-2534)
- Fixed an issue where in rare occasions some repeated API calls resulted in blocked API calls (COC-2505)
- Fixed an issue with importing templates via XML in case a voting template was not saved (COC-2499)
- Fixed an issue with missing parameters in the meeting XML output (COC-2498)
- Added a warning in the CoCon Audio application for creating unsupported configurations (COC-2487)
- Fixed an issue in the CoCon Signage screen where timers were not shown for seats with no delegate assigned (COC-2483)

- Fixed an issue in the CoCon web applications where navigating to localhost:9000 automatically navigates to the CoCon Nameplate Manager and displays an error in case no license is present (COC-2445)
- Fixed UI issues with individual voting results in the CoCon Signage Manager (COC-2433)
- Fixed an issue with the StartMeetingViaXML API for incorrect meeting XML files with group information (COC-2415)
- Fixed an issue with unnecessary API notifications being sent after opening a meeting template in the CoCon Operator application (COC-2401)
- Fixed an issue with resetting voting timers for the CoCon Signage screen (COC-2385)
- Improved image quality on Plixus Nameplates (COC-2195)
- Fixed an in the Audio Routing application where an external language was displayed as an input (COC-2012)
- Added a warning for duplicate delegates in the CoCon Nameplate Manager (COC-1752)
- Fixed an issue where in some occasions the delegate status in the CoCon Operator application was not updated after the connection between CoCon and the central unit (COC-1057)

## KNOWN LIMITATIONS

- Assigning a Plixus Nameplate to a seat requires the user to open and close initialization to update the status (COC-2645)
- In the CoCon Signage screen, the seat label position does not follow the setting from the CoCon Room Configurator (COC-2638)
- In the various CoCon applications, error messages for missing units does not show relevant seat, desk or booth information (COC-2626)
- In the CoCon Video Manager, video input information such as seat and device name are not listed yet (COC-2613)
- The healthIssueOccurred event is currently only sent for Lingua Interpreter desks and delegate units (COC-2066)
- Authority pass with badges is not yet supported on uniCOS units (COC-27)
- Setting the available tabs for the uniCOS interface is not yet available in the CoCon Room Configurator or CoCon Operator (COC-2652)



